

FIELD INSPECTION REPORT

Project Name:	Mountain Valley Pipeline	Inspector:	Matthew Grant
Inspection Date:	Wednesday, April 14, 2021	Project Contact:	Brian Clauto
Spread H: Franklin	AR FR291 & FR290 ATWS 1038, 1039, 1250, 1249 1248, 1247, 1246, 1410	Weather:	Dry

ACTIVE STAGE OF CONSTRUCTION: (Check all that apply)

- ☐ Tree Felling
 ☐ Clearing/Grubbing
 ☐ Grading
 ☐ Trenching
 ☐ Stringing/Welding
☐ Lowering/Backfilling
 ☐ Final Grading
 ☐ Temp. Stabilization
 ☐ Perm. Stabilization
 ☒ Dormant

- | | | Yes | No | N/A |
|----|---|-------------------------------------|-------------------------------------|--------------------------|
| 1. | Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 2. | Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 3. | Areas of offsite sediment deposition observed? | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |

- Comments: Inspected the following resources: S-G26, S-RR18, W-RR4, W-RR3, S-RR16, W-KL41, S-F14
- ECD's were in place and functioning at the designated crossing.

Routine Maintenance: *(72-Hour Deadline from Notification)*

- N/A


Ineffective Controls: *(24-Hour Deadline from Notification)*

- N/A

Recommended Corrective Action: N/A

Deadline: N/A

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature: _____  _____

Date: Wednesday, April 14, 2021

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Wednesday, April 14, 2021

Figure 1: Designated crossing W-EF3, ECD's are in place.



Figure 2: Designated crossing S-RR18, ECD's are in place.




Figure 3: Designated crossing W-RR4, ECD's are in place.



Figure 4: Designated crossing W-KL41 & S-RR16, perimeter ECD's are in place.

